



Geschäftsführer: Herr Gleixner Michael
Herr Scheidacker Maximilian

Bürgermeister-Wiendl-Straße 10 - 92439 Bodenwöhr
Tel.: 09434/ 901 900 Fax: 09434 901 909

Kontakt: Herr Gleixner Michael

		Lohnaufbereitung	Angus/Formteile	MG	Restposten OR / MG	verstärkt GF	unverstärkt	natur	sw	bunt	Mindestmenge	Mindestmenge 500 kg	Mindestmenge 100 kg	Produktionsabfälle	Sonstiger Herkunft	m. Typangabe	off Grade
Thermoplaste	ABS	x	x	x	x	x	x	x	x	x	x	x	x	x	x		
	ASA	x	x		x		x	x			x		x		x		
	ETPU	x															
	LCP	x	x	x	x	x	x	x			x		x		x		
	GPPS	x	x	x	x		x	x	x				x		x		
	MABS	x	x	x	x		x	x	x				x		x		
	SAN	x	x	x	x		x	x			x		x		x		
	SMMA	x											x				
	PE-LD	x	x	x	x		x	x			x		x		x		
	PE-LLD	x	x	x	x		x	x			x		x		x		
	PE-HD	x	x	x	x		x	x			x		x		x		
	PP-HO	x	x	x	x	x	x	x	x		x		x		x		x
	PP-CO	x	x	x	x		x	x	x		x		x		x		x
	PP/TPE	x	x		x		x	x	x	x			x		x		
	PP-TV	x	x	x	x			x	x		x		x		x		x
	PPA	x			x	x	x	x	x				x		x		
	PPE+PS	x											x				
	PPSU	x	x	x	x	x	x	x	x				x		x		
	PS	x	x	x	x		x	x	x	x	x		x	x	x	x	x
	PA 6/66	x	x	x	x	x	x	x	x	x		x	x		x		
	PA6	x	x	x	x	x	x	x	x				x		x		
	PA6/6T	x		x	x		x	x	x				x		x		
	PA6T/6J	x											x				
	PA66	x	x	x	x	x	x	x	x	x			x		x		
	PA10T/XMH	x											x				
	PA11	x	x	x	x		x	x	x				x		x		
	PA12	x	x	x	x		x	x	x				x		x		
	PA 46	x	x	x	x	x	x	x	x		x		x		x		
	PC	x	x	x	x	x	x	x	x		x		x		x		
	PMMA	x	x	x	x		x	x		x	x		x		x		
	POM	x	x	x	x		x	x	x		x		x		x		
	PPO	x	x	x	x	x	x	x	x	x	x		x		x		
PEEK	x	x	x	x	x	x	x	x				x	x	x			
PEI	x	x	x	x	x	x	x	x				x	x	x			
PES	x	x	x	x	x	x	x	x				x	x	x			
PBT	x	x	x	x	x	x	x	x		x		x		x			
PBT/ASA	x											x					
PSU	x	x	x	x		x	x	x				x	x	x			
PPS	x	x	x	x	x		x	x				x	x	x			
PC / ABS	x	x	x	x		x	x	x	x	x		x		x			
PC / PBT	x													x			
PARA	x			x	x	x	x	x				x		x			
TP-Elastomere	TEEE	x										x					
	TPC	x										x					
	TPE	x	x	x	x		x	x	x		x		x		x		
	TPU	x	x	x	x		x	x	x		x		x		x		
	PUR	x	x	x	x		x	x	x		x		x		x		